



LEARNINGS FROM WUERGENDORF ACCIDENTS IN 2002

**Presented at
SAFEX May 2005**



EXPLOSIONS AT WUERGENDORF IN 2002

- The operation
- Presentation of Events
- Contributory causes
- Investigation
- Lessons



INTRODUCTION

- 2 major accidents within 2 months
- Fatality in first accident
- Significant structural damage in both explosions

Herstellung von
Sprengöl
**Manufacturing of
Nitroglycol**

Herstellung von gel.
Sprengstoffen
**Manufacturing of
Dynamites**

Herstellung von Andex
**Manufacturing of
ANFO**

Herstellung von
Emulsions-
Sprengstoffen
**Manufacturing of
Emulsion Explosives**

Lagerung von
Explosivstoffen
**Storage of
Explosives**

Sonstige Gebäude
Other Buildings





STAFF WUERGENDORF SITE

EURODYN Sprengmittel GmbH	88
Orica Germany GmbH	20
DNES	116
DYNAenergetics	20

Total: March 2004 244



PRODUCTION CAPACITIES

Process	Operation Mode	Direct labor	Present output p.a.	Technical capacities p.a.	Utilization rate
Nitroglycol	2 shifts / 5 days	7	4.200 to	5.000 to	84
Dynamites	2 shifts / 5 days	35	12.000 to	15.000 to	80
Emulsions	1 shift / 5 days	2	5.000 to(bulk)	12.000 to	42
		3	320 to (pack)	460 to	70
Anfo Plant	1 shift / 5 days	1	3.400 to	4.100 to	83

Supply Chain: 15
 Lab: 7
 Workshop: 13
 Office: 5
Total: 88

July 2004: 85



DYNAMITES

Paper wrapped:

diameter 22 - 40 mm

length 150 - 380 mm

weight 100 - 625 g

Extruded in PE:

diameter 45 - 100 mm


length 380 - 730 mm

weight 1000 - 5000 g



PRODUCTION LINE FOR GELATINOUS EXPLOSIVES

- 1 Plant for preparation of powder additives
- 2 Transport of powder additives
- 3 Production of nitroglycol
- 4 Transport of nitroglycol by emulsion
- 5 Mixing plant
- 6 Transport of explosive to the feeding station
- 7 Feeding station
- 8 Transport of explosive to the cartridge machine
- 9 Cartridge machine for small diameter
- 10 Cartridge machine for big diameter
- 11 Cartridge machine for rigid shells




NITRATION PROCESS

Continuous- Injector- Process

capacity 750 kg/h/line

Advantages: two separate lines,
remote control,
small amounts of
Nitroglycol





EGDN PLANT CONTROL ROOM





CARTRIDGING LARGE DIAMETER

3 cartridge lines
diameter 45 - 100 mm
capacity 4 - 16 to/shift/line





CARTIDGING SMALL DIAMETER

2 cartridgeing lines
diameter 22 - 40 mm
capacity 2 - 8 to/shift/line





EURODYN Sprengmittel GmbH



Fatal injury
incident at
Wuergendorf site

30.07.2002

1 operator killed



THE OPERATION



Manufacture and Packaging
of Dynamite

Small Diameter

- wrapped in paper

Large Diameter

- wrapped in PE
- 2 shifts working 8 hrs each
- senior operation people
on site on day of accident



1st INCIDENT

30 July 2002

- Building 49: Dynamite small diameter Packaging Machine: Rollex
- Machine exploded while employee was in room; around about 90 kg of Dynamite
- Possible causes: Foreign body introduced to either Auger or table
- Consequences: one fatality, Machine and Building destroyed

WHAT HAPPENED?



Above transfer tunnel

SEQUENCE OF EVENTS

Monday, 30 July 2002

- 4.08am Operators start arriving for work
- 5.15am Operators arrive at Processing Room, set up for production of Rollex (manning - 2 operators, one services machines, one packs product, in separate buildings)
- 5.30am Rollex Machine starts up, operators rotate, go for breakfast during morning
- 11.00am Fitter makes adjustment to machine, operators take turns for lunch break. Cleaning activity and poor quality cartridges returned.
- 12.35pm One operator returns to Rollex Room
- 12.50pm Explosion occurs

Problems on day

- Paper feed/adjustment, cartridge ejection, feed belt sticky, pusher, shear pin failure

EMERGENCY RESPONSE



Roadway

- Handled by Site Permit Holding Company
- Used existing procedures, full liaison with Police and Regulatory Authorities

EXPLOSION



Entrance to cartridging room

- Occurred in a dynamite cartridging room (Rollex Machine)
- Approx. 90 kg NG explodes
- **One Fatality**
(Bruno Itschner,
 - 36 years - married, no children
 - 10 years' experience
 - 2 years in NG on Rollex Machine))
- **No other casualties** - fortunate as debris (broken concrete, steel, earth, etc.) rained down over adjacent operating areas
- **Extensive damage** (projectile and overpressure) in immediate area to equipment, building and roadways, up to 120 metres from blast.
- **Machine in 2000 pieces**

WHY DID IT HAPPEN?



Feeding Station

Investigation

- **Local team set up to:**
 - manage clean up and recovery of equipment
 - gather background data
 - preliminary investigation
- **Company Team formed:**
 - formal remit,
 - external consultants involved,
 - followed 5-step process
- **Steps involved:**
 - interviewing employees
 - analysis of projectile path
 - re-construction of machine/forensic examination
 - examining system failures
 - preparing a root cause analysis (why diagram)



CONTRIBUTORY CAUSES ACCIDENT 1

- Operator in vicinity of Cartridging room when operating
- Work practises with no sound basis of safety
- Engineering changes with inadequate risk evaluation
- Management and employees lost basic understanding of design philosophies and operational intent of the processes
- A number of likely ignition sources were identified
- Foreign body in Stainless steel feed auger



CONTRIBUTORY CAUSES ACCIDENT 1 (Cont'd)

- Dropping of heavy waste tray
- Foreign body between steel knife and steel trough at end of packing table
- Waste process was changed just before explosion, smaller bins for waste explosive much more difficult to scrape trays into
- Trough of machine had been changed from plastic to steel



COURSE OF INVESTIGATION

- Looking for fragments of machine components and identification of this - documentation on maps
- Re-assembling of fragments if possible
- Trace analysis for possible cause at this fragments
- Check of used raw material and already produced cartridges
- Check of Quality Control documentation
- Looking for process cycle weaknesses
- Check of complete data's of production day (malfunctions of machine, time steps in production e.g.)
- Inspection of service and maintenance notes
- Interview of second operator




1st INCIDENT





EXPLOSIVES IN PROCESS



Amount of explosives from experience routine end of production 80-90 kg

COURSE OF INVESTIGATION

Looking for machine components



Revolver

2 cartridges insite



1st INCIDENT





SPECIFIC FINDINGS

- The victim was in the vicinity of the explosive cartridging room in breach of standard work practices. Whether he contributed in any way to the explosion could not be determined and because of the extent of damage caused by the explosion this may never be determined.



FINDINGS (2)

- Over the thirty years that this particular cartridging machine and associated facilities had been operated work practices have evolved which do not have a sound safety base taking into consideration that explosives were being handled. Complacency to the hazards and risks associated with NG based explosives has crept into the organisation at all levels on the site.



FINDINGS (3)

- Engineering changes had been made with little or no concern to the hazards and risks at hand. Many of these changes had been made some years ago and at the time may have been based on sound safe operational and engineering assessments. The reasons for such changes have been lost or forgotten in the current management structure.

FINDINGS (4)

- A number of likely ignition sources for the explosion were identified but none could be determined as the main source of ignition. A foreign body catching in the stainless steel feed auger or at the knife of the cartridging machine are regarded as highly probable ignition points but whether this foreign body was introduced further up-stream in the process or inadvertently by the operator could not be determined.

FINDINGS (5)

- Another possible ignition source could have been the accidental dropping of a heavy waste tray by the operator. This possibility is supported by sensitivity calculations and the fact that a change to explosive waste collection was made some weeks prior to the accident.

CONCLUSION



Searching for machine components

Management and employees at the factory not mindful of

- Design philosophies and operational intent of their operation
- Basic associated safe systems of work



What did we learn?



Feeding Station



WHAT DID WE LEARN ?

- Control of change, a vital safety element
- Importance of behavioural safety
- Importance of continuously reviewing plant and process
- Control of Foreign bodies, screws to personnel jewellery
- Visitors limited and controlled
- Production procedures and plant design need constant [review](#)
- Video control of process [continuously](#)
- Modification of work instructions (pictures vs. text)
- Other design of workwear, eliminate pockets
- Check of routines for shift change over



2nd INCIDENT

30 September 2002

- Building 207: Third wash process of EGDN.
- Explosion in building after production start over a weekend, around about 60 kg of EGDN.
- Possible causes: friction in ball valves of the EGDN transport; Vacuum forced EGDN to collapse.
- Consequences: Building and machinery destroyed.
- Last event prior to the explosion was the commencement of NG transport to the storage house which involved the remote opening of the valve.



BALL VALVES





2nd INCIDENT








NITRATION PROCESS

Continous- Injector- Process

capacity 750 kg/h/line

Advantages: two separate lines,
remote control,
small amounts of
Nitroglycol





Remote control of NG plant by computer





NITRATION PROCESS

Capacity: 2x 750 kg/h
= 1500 kg/h

No damages

Only minor flying bricks



Building 200 (one of two Nitrators & Related Equipment)

Centrifuge

$n = \text{ca. } 3500 \text{ min}^{-1}$

Safety issue:
Acidic nitroglycol
in centrifuges
(appr. 1 - 2 kg)





**Wash Building
204 after
explosion**

**Safety issue:
Disposal of
nitroglycol
contaminated
material (liquid/
solid) in a bund**





2nd INCIDENT





**Testing Vessel
Building 208**

**Safety issue:
approx. 400 kg
nitroglycol in
vessel**





Pump Building 207.1
Partly damaged





SAFETY ISSUES IMMEDIATELY AFTER INCIDENT

Priority	Location	Situation
1	Wash house 204 Wash & filter house 208	appr. 200 - 400 kg nitroglycol contaminated material (liquid/solid) in each bund
2	Centrifuge houses 201 and 202	appr. 1- 2 acidic nitroglycol in each centrifuge
3	Final wash & filter house 208	appr. 400 kg pure nitroglycol in vessel/separator
4	Storage houses 062 and 063	appr. 40 - 100 kg pure nitroglycol in building 062, appr. 1000 - 1200 kg pure nitroglycol in building 063
5	Destroyed final wash & filter house 207	nitroglycol contaminated ground and soil

RECOMMENDATIONS FOR WUERGENDORF FACTORY




**Turrent and frame of Rollex
cartridge machine**

Extensive action list (36 items) from investigation covering:

- previous audit action close-out
- site procedures
- safe operating procedures
- process safety (BOS)
- hazard studies
- protection systems
- remoting high risk operations
- re-training
- reinforce adherence to standards
- formal review of completion prior to re-start



“Task Deviations” Accident Model



LESSONS



Frame of Rollex machine was covered with 2 metres of debris

FOR ACQUISITIONS

- Due diligence to include process safety as well as SH&E Leadership/Management
- Understand the process and critical controls
- Identify gaps and action accordingly

LESSONS (cont'd)



Individual items numbered and photographed

FOR ALL ORICA OPERATIONS

- Reinforcement by management of adherence to safe systems of work (need to be fully implemented to be effective)
- Awareness of dependence on core systems
 - procedures (safety operations, maintenance, etc.) in place and followed
 - training is adequate
 - timely close out of audit and incident actions
- All employees to be vigilant and mindful of potential hazards in processes and materials
- Inherent process safety (Basis of Safety) understood, standards maintained and non-conformances are detected and investigated.

LESSONS (cont'd)



Projectile Analysis on a plot diagram

FOR ALL ORICA OPERATIONS

- Critical processes identified using Periodic Hazard Study procedure
 - identify hazards
 - assess risks
 - controlled risks through design, procedures and training
 - audit
- Internal audit programs effective
- External audit programs target more closely operational level.

DO WHAT WE SAY!



OTHER OUTCOMES

- Strengthened hazard studies and training in the German organization
- Management changes at Wuergendorf
- A review of acceptable FAR criteria, which has led to a focus on truly remoting this dangerous process
- Strengthening of audit action close-out process
- Scheduled BOS audit of Troisdorf processes



OTHER OUTCOMES (cont'd)

- An operational review of procedures and safe work instructions across Orica globally
- Acceleration of the Basis of Safety renewal process within the Explosives Group, which will be directed by a Review Board and which will include a mandatory audit program once the new documents are available.