





Austin

Powder GmbH

Austria

Heinz Krätschmer



Deflagration of
Nitrocellulose
in the Lab



What happened?


- ◆ January 7th 2002, 07:56 am
- ◆ Explosion in room #11 of the lab
 - deflagration of app. 800 g NC
inside a convection oven
 - temperature in the lab 18 °C (64 °F)
 - outside temperature -3 °C (27 °F)
 - relative humidity 55 %



Injuries/Damages

- ◆ no people injured
- ◆ room #11 extensively damaged
- ◆ rooms #10 and #12 and ceiling of the building damaged
- ◆ most windows of lab building broken
- ◆ some smaller damage in the lab
- ◆ total cost app. \$ 180,000

Plan of the laboratory



Room #11



Room #11 convection oven



Room #11 drying tray



Room #11 outside view



Room #12 wall/ceiling damage



Room #4



Room #9



Lab main entrance



SA



Process Description

- ◆ NC (wetted with 35 % Ethanol) dried in convection oven at 50 °C (122 °F, 1 week)
- ◆ NC in the oven placed on an aluminum tray
- ◆ Dry NC used for lab scale manufacturing process
- ◆ Excess dry NC added to next batch for drying
- ◆ 10 years at DNW, before 40 years in another company without any problems



Possible Causes

- ◆ *overheating of convection oven*
- ◆ *electrical defect in convection oven*
- ◆ *inhomogeneous temperature dispersion in the convection oven*
- ◆ *electrostatic discharge*
- ◆ *fire outside convection oven*
- ◆ *explosion of ethanol vapors*
- ◆ *too long drying period (Xmas)*
- ◆ *thermal instability of NC*



Investigation Results 1

- ◆ *no overheating, temperature checked some minutes before, thermal fuse 80 °C (176 °F)*
- ◆ *no electrical defect according to examination by expert*
- ◆ *identical oven showed homogeneous temperature dispersion*

Investigation Results 2

- ◆ *no electrostatic discharge according to examination by expert*
- ◆ *no fire outside the oven according to examination by expert*
- ◆ *no explosion of ethanol vapors because no ethanol left after 2 weeks*

Investigation Results 3

- ◆ Investigation of thermal stability of the NC batch showed a decrease in stability when stored on aluminum trays at elevated temperatures
- ◆ traces in the drying tray show some evidence of a starting explosion
- ◆ manufacturer of NC reduced shelf life of NC type to one year, but did not inform us
- ◆ batch used was app. 2 years old



Actions

- ◆ *adaptation of a separate building for drying and further processing of NC*
- ◆ *drying process remote controlled*
- ◆ *special drying oven with hot water heating and explosion proof ventilation*
 - *oven temperature 30-35 °C (86-95 °F)*
 - *NC dry after 20 hours*
- ◆ *stainless steel drying trays*
- ◆ *excess of dry NC is destroyed*



Actions

- ◆ *NC batch used for 1 year max.*
- ◆ *manufacturer of NC asked for MSDS at regular intervals*
- ◆ *inspection of process building by responsible manager at regular intervals*
- ◆ *use of safety glass for all lab windows*



Lessons learned

- ◆ Do not take over a process designed outside the company without doing an in house risk assessment
- ◆ Audit the process for possible changes on a regular basis