

# Explosion during primary explosive process

---

Presented by Tsuyoshi MURASHITA  
ASAHI KASEI CHEMICALS CORPORATION  
JAPAN  
May 27 2005


XV CONGRESS SAFEX INTERNATIONAL

AsahiKASEI

## Background

---

- DDNP powder is produced as a primary explosive of electric detonator.
- DDNP powder is granulated in continuous production process.



Granulated DDNP powder

XV CONGRESS SAFEX INTERNATIONAL

AsahiKASEI

## Background

□ The process consists of mixers, a granulator, dry conveyors, a measurement device, and a takeout robot.

□ Operators are able to check the status of machines by remote controlled TV monitors and small windows that are located at the concrete wall.



Operating room





Remote TV monitor

XV CONGRESS SAFEX INTERNATIONAL

AsahiKASEI

## Outline of the process



Layout view of the accident place

XV CONGRESS SAFEX INTERNATIONAL

AsahiKASEI

## Composition of DDNP powder




Table Composition of DDNP Powder


Materials	Wet	Dry	
	Composition (wt%)		
DDNP (Diazodinitrophenol)	42.69	49.84	
KClO <sub>3</sub> (Potassium chlorate)	42.69	49.84	
Water-soluble cellulose ether (Binder)	0.09	0.10	
Powder for preventing static electricity	0.02	0.02	
Ethanol / water (wt%: 50/50)	14.51		
Water		0.20	
<b>Total</b>	<b>100</b>	<b>100</b>	
Sensitivity	Drop-Hammer test	Grade 1	Grade 1
	Friction sensitivity	Grade 1	Grade 1

XV CONGRESS SAFEX INTERNATIONAL

AsahiKASEI

## Accident

- At 8:58 on Wednesday, 12th June, 2002, an explosion occurred in the continuous production process of DDNP powder.
- Approximately 2.6 Kg of DDNP powder fired and detonated.
- No persons were injured.



Layout view of the accident place

XV CONGRESS SAFEX INTERNATIONAL

AsahiKASEI

## Damage



Granulator

XV CONGRESS SAFEX INTERNATIONAL

AsahiKASEI

## Damage



dry conveyor

XV CONGRESS SAFEX INTERNATIONAL

AsahiKASEI

## Damage



□ d dry conveyor  
and ceiling

XV CONGRESS SAFEX INTERNATIONAL

AsahiKASEI

## Damage



Outside view of  
the accident place

XV CONGRESS SAFEX INTERNATIONAL

AsahiKASEI

## Analysis


- Where did it ignited ?
- How did it ignited ?
- Why did it happen ?

XV CONGRESS SAFEX INTERNATIONAL

AsahiKASEI

## Where did it ignite ?

- The ignition occurred around granulator.
  - Remained the detected signals in the control unit
  - Initiation sensitivity property of DDNP powder




XV CONGRESS SAFEX INTERNATIONAL

AsahiKASEI

## How did it ignite ?

- The fire propagated to DDNP powders on the conveyor.
- The status of combustion was changed to deflagration and finally detonation occurred.



XV CONGRESS SAFEX INTERNATIONAL

AsahiKASEI

## Why did it happen ? (1)

- The crack of plate made by PVC
- The residue of DDNP powder inside the crack.
- Grown the crack of PVC plate in the bended part
- Separated the plate
- Ignition of the residue of DDNP powder by the impact and friction



XV CONGRESS SAFEX INTERNATIONAL

AsahiKASEI

## Why did it happen ? (2)

- ❑ Generated rust in the stopper of the equipment to supply DDNP powder
- ❑ Mixing the DDNP powder and rust in the granulator
- ❑ Increased ignition sensitivity of the mixtures
- ❑ Ignition of the DDNP powder by the impact and friction in the granulator



XV CONGRESS SAFEX INTERNATIONAL


AsahiKASEI

## Action to prevent recurrence


- ❑ Improvement of the part made by PVC
- ❑ The parts that can be the cause of rust were improved.
- ❑ Reeducation to operators concerning the accident
- ❑ Dangerous potential of primary explosive residue inside the parts
- ❑ Importance of thorough cleaning of equipments
- ❑ Improved the inspection system for equipments

XV CONGRESS SAFEX INTERNATIONAL

AsahiKASEI



Before



After



### Improvement of stopper and dry conveyor

XV CONGRESS SAFEX INTERNATIONAL

AsahiKASEI



Before



After



### Improvement of dry conveyor

XV CONGRESS SAFEX INTERNATIONAL

AsahiKASEI